

- The measurement of quartz crystal units is based on PI Network as below.
Standardized in IEC60444

- The quartz crystal parameters are determined by mathematical algorithms from measured data.

Such as C_0 , C_1 , L_1 , R_1

